




Worksurface Power - EC26




- Remove clamping bracket from power unit.
- From top side of table, feed power cord through cutout in worksurface and lower unit onto surface.
- Reattach clamping bracket from underside of table, tighten four screws firmly.
- Route cord through wire manager accordingly.



Under Surface Power - EC27



- Locate center of table.
- Position power unit in center of table from right to left and offset front of power unit back $\frac{1}{8}$ " from front edge of table.
- Mount using four supplied screws.
- Route cord through stretcher panel and wire manager accordingly.



Edge Mount Power - EC28



- Position power unit in desired position along back edge of table.
- Tighten both clamp knobs firmly.
- Route cord accordingly.

Notice To Installers: Failure to comply with installation instructions will compromise the safety, durability and performance of this product, which may risk injury to the user of this product and/or diminish the product life cycle. Jasper Group assumes no liability in these instances.